













## CI-1000 Tips

Description	Image
<u>1</u> Universal tip for 2.5mm male PC- type connectors	 CI-1000-U2.5/PC/M
<u>2</u> Universal tip for 1.25mm male PC- type connectors	 CI-1000-U1.25/PC/M
<u>3</u> Universal tip for 2.5mm male APC- type connectors	 CI-1000-U2.5/APC/M
<u>4</u> Universal tip for 1.25mm male APC- type connectors	 CI-1000-U1.25/APC/M

<u>5 &amp; 6</u> Tip for FC/PC female connectors (Tip body with FC-guide mounted)	 +  CI-1000-SC/FC/F + CI-1000-FC/G
<u>5 &amp; 7</u> Tip for SC/PC female connectors (Tip body with SC-guide mounted)	 +  CI-1000-SC/FC/F + CI-1000-SC/G
<u>8</u> Tip for LC/PC female connectors	 CI-1000-LC/F
<u>9</u> Tip for FC/APC female connectors	 CI-1000-FC/APC/F
<u>10</u> Tip for SC/APC female connectors	 CI-1000-SC/APC/F
<u>11</u> Tip for LC/APC female connectors	 CI-1000-LC/APC/F